

Informations techniques/Technical Matters

Industries Bouchard, Inc.
 FILIALE - SUBSIDIARY
 GIFFEN RECREATION

 La Pocatière, P.Q., Canada
 code 418 tél.: 856-1232
 télex: 011-3486
DATE October 13rd, 1970.

On the model M.S. 18, it was reported that the tail lamp harness is too short limiting the access to the tool box.

To correct this incident, an extension reference no. 73-01-180 has been designed and is available at the Central Parts Depot.

In the field proceed as follows:

- 1° Disconnect the multiple connector located in the front of the engine;
- 2° connect the extension in the connector block;
- 3° pull the harness in the tool box to pick the necessary slack.

This operation will carry the STO 49.007 and this number has to appear on the warranty claim.

It will be permissible to claim for several machines on the same claim form provided that the serial numbers are clearly written and are unit unsold at the distributor or dealer level.

No time allowed for this operation.

Yvon Arpin
 Yvon Arpin,
 Director of After Sale Services.

YA/CB

