

Informations techniques / Technical Matters**Industries Bouchard, Inc.**

La Pocatière, P.Q. Canada
code 418 tél.: 856.1232
téléc.: 011-3486

DATE November 3rd 1970.SUBJECT: POLYCARBONATE HOODS.

Between the serial no. 33,650 to 34,900, it has been reported a paint peeling condition of the hood. Before delivery of a snowmobile to a customer, it is imperative to replace the defective hoods by a new one unpainted.

These hoods are available at the Central Parts Depot under the reference no. 73-01-004 and they should be ordered through the usual channels.

At the same time, make sure that the decals corresponding to the model are ordered; this is the reason why we cannot supply these hoods assembled for replacement.

To replace, proceed as follows:

- 1° Remove the complete hood,
- 2° remove all the electrical components and harness,
- 3° remove the ventilation scoops,
- 4° re-assemble.

The flat rate allowance is \$7.50, (including transportation charges).

The STO number: 49,009 has to be shown on all the warranty claim submitted for approval and the hoods replaced must be returned to your distributor, for inspection.



Yvon Arpin,
Director of After Sale Services.

YA/CB