

**Informations techniques / Technical Matters****Industries Bouchard, Inc.**

La Pocatière, P.Q. Canada
code 418 tél.: 856.1232
téléc.: 011-3486

DATE November 3rd, 1970.SUBJECT: 1971, 295CC UNITS EQUIPPED WITH KEI-HIN CARBURETTORS, TYPE 406.

This note is an addition to the circular T-70-08.


The two conditions reported on the Mini-Sno equipped with a KEI-HIN carburettor applies to the above mentioned units.

A standard exchange program is set through your distributor to replace these carburettors and these are available at the Central Parts Depot through the usual channels.

The following STO numbers will have to be shown on the warranty claim:

STO	49.005	for carburettors replaced on 295CC engine (1971 models).
STO	49.010	will apply for 1970 Mini-Sno, equipped with a HR25A Tillottson carburettor (see circular T-70-08 paragraph "A").
STO	49.012	1971 Mini-Sno equipped with 406 KEI-HIN carburettor (see circular T-70-08, paragraph "B").
STO	49.013	1970 models equipped with a 407 KEI-HIN carburettor (see circular T-70-08, paragraph "C").

Time allowed for the replacements of a carburettor is \$1.00. There is no allowance for a replacement under STO 49.013 (needle and seat).


Yvon Arpin,
Director of After Sale Services.

YA/CB