

**Informations techniques/Technical Matters**

September 7, 1971.

DATE _____

SUBJECT: 1972 TYPE BACKREST.

Please advise all your dealers, that the following procedure must be applied, in order to prevent damage to 1972 type backrest.

Before trying to open or gain access to the compartment behind backrest, the two (2) lower snaps (one each side of lower frame) must be undone before trying to pull backrest forward.

RECOMMENDATION FOR SHOWROOM SLEDS.

It would be advisable that dealers with showroom sleds leave these two snaps undone to prevent damage by unknowing prospective customers.

RL/cm

Technical Information Department.