

Informations techniques/Technical MattersDATE October 7th, 1971.SUBJECT: ZEPHYR TRACK 1972.

The Zephyrs, powered by a BSE-340 engine, are equipped with a 47 cleat track, part #030105 (old 03-00-002).

The Zephyrs, powered by a BSE-440 engine, are equipped with a 46 cleat track, part #030031 (manual and electric start).

The above tracks are not interchangeable because it is impossible to adjust the tracks properly.

If interchanged, it would result in the damage of the sproket and the track.

RL/lb

Technical Information Department.